

LOW PRIORITY REPAIR OCCURRENCES

Traffic Signals/Pedestrian Crosswalks

Low Priority (Scheduled Work)

- Pole Leaning;
- Pole Handhole Cover Missing (high priority if unsafe);
- Back Guy/Anchor Loose/Damaged;
- Riser Damaged;
- Dark Spot in Signal Head;
- Water in Signal Head;
- Detection System Faults (where temporary repairs have been made);
- Loss of Communication Lines;
- Communication Faults;
- Central Traffic Control System Faults;
- Push Button Stuck/Loose/Damaged (but still operational);
- Internally Lit Overhead Sign Burn Out;
- Signal Pole Oscillations;
- Dynamic Message Sign Not Working;
- CCTV System Faults;
- Data Sampling Station Faults;
- Overheight Detection System Faults.